

PET Felt Cleaning and Care



CLEANING

Polyethylene Terephthalate (PET) felt can be vacuumed to remove dust. For spills and stains, blot away any excessive moisture from spills off the material as quickly as possible. Wipe the area with a damp cloth and blot dry. If the staining persists, apply a small quantity of carpet cleaner mixed with water on a dampened cloth. Blot well after each application. Make sure to test this procedure in a discreet area before you use it in a visible area.

DISINFECTING

If there is a need for infection control, bleach can be used in accordance with CDC Cleaning and Disinfection instructions. The solution ratio should be 5 tablespoons of bleach to 1 gallon of water or 4 teaspoons of bleach per quart of water. Apply the solution as a mist and then wipe off the surface moisture to help spread the solution.

Always try these methods in a discreet place on the product prior to using on a visible area.

